

IN THE OFFICE OF THE STATE ENGINEER
OF THE STATE OF NEVADA

O R D E R

Mr. Carl Uhlig, Water Master
Pacific Reclamation Company
Metropolis Road
Wells, Nevada 89835

This office has determined by field investigation that the Bishop Creek Dam located in Section 24, T.39N., R.62E., M.D.B.&M., is an unsafe structure having developed a significant leak resulting from deterioration of the cement cap on the upstream face of the dam, the dam, therefore, has become a hazard to both life and property.

You are hereby ordered, under the provisions of Nevada Revised Statute 535.030, to empty the reservoir by lowering the level of water at a rate not to exceed one (1) foot per day until the impoundment is drained.

The reservoir shall remain empty until plans and specifications for repair or reconstruction, as required under NRS 535.010, are submitted to the State Engineer and approved. Upon approval, all repairs or reconstruction of the dam and related structures must be accomplished and the dam determined to be repaired or reconstructed in compliance with the approved plans and specifications before any impoundment of water is allowed.


Peter G. Morros
State Engineer

Dated at Carson City, Nevada,
this 3rd day of JULY, 1984.