

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 105495
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

Clark County 29

NOTICE OF INTENT NO. _____

1 OWNER Public Right of Way on Desert Inn Road
MAILING ADDRESS 500 South Grand Central Parkway
Las Vegas, Nv 89101

ADDRESS AT WELL LOCATION Public Right of Way on Dessert Inn Rd.
Subdivision Name: Emergency Sewer Repair County: Clark

2 LOCATION SE $\frac{1}{4}$ SW $\frac{1}{4}$ Sec 10 T 21S N/S R 62 E
PERMIT/WAIVER No. DW-1266 16110499002
Issued by Water Resources Parcel No. _____

Latitude _____ UTM E NAD 27
Longitude _____ N NAD 83/WGS 84

3 Temp De-watering TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____

Is there an existing well log? yes
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 30 Feet Depth Cased 30 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	30

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: _____

Existing Perforations:

Type of perforation	Size of perforation	From	To
machine slotted	0.032	10 feet	30 feet

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL
Static water level 12 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
30	12	feet	concrete slurry	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12	surface	feet	fill	<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

Well was next to sewer pipe being repaired. Well was consumed by exavation and filled with concrete slurry to top of sewer pipe, then covered with compacted fill

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 4/8/2008
Date Completed 4/8/2008

(Rev. 05-06)

MAY 12 2008

LAS VEGAS OFFICE

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Viking Drillers Inc. Contractor
Address 801 Northport Dr. Contractor
West Sacramento, CA 95691
Nevada contractor's license number issued by the State Contractor's Board 0034680
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2091
Signed _____
Date 5/7/2008
By driller performing actual drilling on site or contractor

USE ADDITIONAL SHEETS IF NECESSARY

209 105495



VIKING DRILLERS, INC.

Dewatering Systems

801 Northport Drive
West Sacramento, CA 95691-2153
(916) 372-4993 • FAX (916) 372-1337
www.vikingdrillersinc.com
California License #476668



May 7, 2008

Tracy Geter
Nevada Division of Water Resources
400 Shadow Lane, Room 201
Las Vegas, NV 89106

Re: DW-1266 Well Completion Reports

Dear Tracy,

Per our conversation, enclosed are the Well Drillers Plugging Reports for the one (1) temporary dewatering wells drilled along the Public Right of Way on Desert Inn Rd. for the Emergency Sewer Repair work. These wells were directly adjacent to the pipeline being repaired and during the repair work the wells were completely consumed. As a result, there were no wells to abandon. Additionally, because of the unpredictable timeline for this emergency repair work and the need to expedite construction, a NOI card for well abandonment was not filed. Once again, these wells were temporary dewatering wells.

Sincerely,


Sean LaChapelle
Area Manager

