


Log# 36854



NENW 7 16N 22E

BOBBY L. BARNES  
BARNES WELL DRILLING  
7061 HWY 50 EAST  
DAYTON, NV 89403

JULY 1, 1991

DIVISION OF WATER RESOURCES  
123 W NYE LANE  
CARSON CITY, NEVADA 89710  
ATTN: THOMAS K. GALLAGHER

RE: PAT COLIVA  
LOG #34400 (original completion)

DEAR MR. GALLAGHER,

THIS IS TO ADVISE YOU I ATTEMPTED TO PLACE A CONCRETE PLUG IN THE BOTTOM OF THE ABOVE REFERENCED CUSTOMERS WELL BUT I WAS UNABLE TO GET THE CONCRETE TO SEAL THE BOTTOM. THE CONCRETE WAS PUMPED IN AT THE BOTTOM BUT EVIDENTLY IT DIDN'T SEAL THE WELL AS IT CONTINUED TO HEAVE.

I WENT BACK APPROXIMATELY 2 MONTHS LATTER WHICH WAS ABOUT TWO WEEKS AGO AND HAVING FOUND THE CONCRETE DID NOT SEAL THE BOTTOM I PLACED RIVER ROCK APPROXIMATELY 3 FEET UP IN THE BOTTOM OF THE WELL WHICH SHOULD TAKE CARE OF THE PROBLEM.

  
BOBBY L. BARNES, OWNER  
BARNES WELL DRILLING

June 1991

2000

2000