LOG OF FORMATIONS—*Continued*

From feet	To feet	Thickness	Type of material
			NOTE: There is a break in the casing at 179' - indications are that this break was caused by the earthquake in 1955. The well was cased to 350' but the under soil has pussed up to 279'. The casing is bent from 140' and 12" bowls will only go down to 130'

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

11-18-59 Well tested and pumped 1,000 GPM from 110'

Well yield rated at 10.7 GPM per foot of drawdown.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed Bruce Boswell
~~Well Driller~~
Water Development Engineer
XXX By 2171 East Second
Reno, Nevada
License No.

Dated 11-20, 19 59

(Not to be filled in by Driller)