WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 3921
Rec. Nov. 4 1957
Well No.
Permit No.
Do not fill in

Owner ROBERT JOHNSON JR. Driller JESSE J. HARRISON
Address HOT SPRINGS Rd. CARSON City Address HARRISON LANE, Hot Springs Rd. CARSON City Lic. No. 6

Location of well: NE 1/4 SE 1/4 Sec. 4, T. 15 N/S, R. 20 E, in ORMSBY County

or about 500' west of HARRISON LANE ON HOT SPRINGS Rd.

Water will be used for DOMESTIC PURPOSES Total depth of well 45'

Size of drilled hole 10" Weight of casing per linear foot 10.085 ft.

Thickness of casing 1/4" Temp. of water COLD

Diameter and length of casing 4" X 45'
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure

If nonflowing well give depth of standing water from surface 24'

If flowing well describe control works
(Type and size of valve, etc.)

Date of commencement of well Sept. 25th Date of completion of well Sept 27-57

Type of well rig ROTARY

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	2	2	top soil
2	30	28'	Hard pan
30	45	15	sand & Gravel

This is a Repair job took out old casing and Replaced with some new casing some was in good shape, sunk well down 10 ft deeper than original well

1957 NOV 4 AM 10 [illegible]
STATE ENGINEER
OFFICE

Water-bearing Formation, Casing Perforations, Etc.

Chief aquifer (water-bearing formation)
from 30 to 45 ft.

Other aquifers none

First water at 30 feet.

Casing perforated
from 30 to 45 ft.

Size of perforations
3/16 x 6" 3 rows around casing 6" apart.

(OVER)

919

LOG OF FORMATIONS—*Continued*

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.
4"	0	45	45	Repair job took out casing and replaced some with new casing. Perforations in old casing were closed up. Well was not deep enough in gravel. Good quality 4" threads & collars standard 4" — 1/4" thick wt. 10.088 per ft

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

This well did not supply 100 gals per hr before Repair

Bailed at 250 gals per hr 5 ft draw down

Owner Installed jet pump well supplies all pump can handle and well does not run short.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed Jesse J. Harrison
Well Driller

By

License No. C

Dated Nov. 2nd, 1957

OFFICE
STATE ENGINEER

1957 NOV 4 AM 10 06

(Not to be filled in by Driller)