#5

WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 4258
Rec. Sept 17 1958
Well No.
Permit No. 18913 Do not [illegible]

Owner: Wine Cup Ranch Driller: Harry Bolton

Address: Wilkens Nevada Address: Twin Falls Idaho Lic. No. 179

Location of well: S.W. ¼ N.W. ¼ Sec. 27, T. 43 N/S, R. 66 E, in Elko County County

or

Water will be used for: None Total depth of well: 450

Size of drilled hole: 8" Weight of casing per linear foot

Thickness of casing Temp. of water

Diameter and length of casing
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure

If nonflowing well give depth of standing water from surface

If flowing well describe control works
(Type and size of valve, etc.)

Date of commencement of well: July 19 Date of completion of well: July 26 1958

Type of well rig: Churn

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	263	263	Clay & Gravel
263	278	15	Conglomerate
278	415	137	Clay & Gravel
415	420	5	Gravel
420	450	30	Clay

DRY HOLE

(OVER)

Water-bearing Formation, Casing Perforations, Etc.

Chief aquifer (water-bearing formation)

from ..... to ..... ft.

Other aquifers

First water at ..... feet.

Casing perforated

from ..... to ..... ft.

Size of perforations

919

LOG OF FORMATIONS—*Continued*

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed Harry Bolton
Well Driller

By

License No. 179

Dated Sep 13, 1958

(Not to be filled in by Driller)

1958 SEP 17 AM 11 07

STATE ENGINEER
OFFICE