WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 7829
Rec. May 13 1964
Well No.
Permit No.
Do not fill in.

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY

Owner Mark West Developement Co. Driller Nevada Pump and Irrg. Co.
Address 130 Vassar St Reno Address 1500 So. Virg Reno Lic. No. 6648

Location of well: SW ¼ NE ¼ Sec. 7, T. 20 N/S, R 19 E, in Washoe County

or

Water will be used for Domestic Total depth of well 737

Size of drilled hole 12 1/4" Weight of casing per linear foot 16.8

Thickness of casing .188 Temp. of water Cold

Diameter and length of casing 8 1/4"x 550'
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure

If nonflowing well give depth of standing water from surface

If flowing well describe control works
(Type and size of valve, etc.)

Date of commencement of well 9/ 15/63 Date of completion of well 9/23/63

Type of well rig Rotary

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	8	8	Clay and Rock
8	60	52	Red Clay
60	90	30	Red Clay
90	737	647	Clay and Broken Rock

Water-bearing Formation, Casing Perforations, etc.

Chief aquifer (water-bearing formation)

from to ft.

Other aquifers A little drilling mud was lost at 340 - 380 well was blown but very little water was obtained.

First water at feet.

Casing perforated

from 480 to 550 ft.

Size of perforations

1 1/8" x 8" Burned

(OVER)

919

LOG OF FORMATIONS—Continued

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	REMARKS—Seals, Grouting, etc.
8 1/4"	0	550'	550'	Well was graveled and some developedment done with air but very little water was available. Grout seal was poured to 35', mixture of Bentonite and cement.

GENERAL INFORMATION—Pumping Test, Quality of Water, etc.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed Earl Funk
Well Driller

By

License No. 405

Dated 9-25, 1963

(Not to be filled in by Driller)