WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 10287
Rec. ..... 19.....
Well No. .....
Permit No. 22617
Do not fill in.

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY

Owner Charles Nelson Driller Dave McNinch

Address Winnemucca Nevada Address Box 585 Winnemucca Nev Lic. No. 219

Location of well: ¼ ¼ Sec. ....., T. ..... N/S, R. ..... E, in Humboldt County

Permit No. .....

Water will be used for Irrigation Total depth of well 520

Size of drilled hole 14½" Weight of casing per linear foot 25#

Thickness of casing ¼ Wall Temp. of water Mild

Diameter and length of casing 14" To 138' - 12" 138-460' 10" 460-520'
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure .....

If nonflowing well give depth of standing water from surface 45'

If flowing well describe control works .....
(Type and size of valve, etc.)

Date of commencement of well ..... Date of completion of well worked on well March 1968

Type of well rig Cable Tool

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	460	460	drilled By Armstrong Bros, formations unknown for certain. evidence of lots of Clay + Rock. Some water strata's with gravel were hit but don't know at what level. Tools had been lost in well, had to be sidetracked from 460 down.
460	503	43	Red clay some Rock.
503	510	7	Clean fine gravel.
510	515	5	Clay
515	520	5	Clean gravel

1968 OCT 17 AM 10 02
STATE ENGINEER
OFFICE

(OVER)

Water-bearing Formation, Casing Perforations, etc.

Chief aquifer (water-bearing formation)

from ..... to ..... ft.

Other aquifers .....

First water at 60 feet.

Casing perforated

from 60 to 300 ft.

Size of perforations

3/8 x 2½" Slots To 300
¼ x 2" Factory Slots 300 To 460

919

LOG OF FORMATIONS—Continued

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	REMARKS—Seals, Grouting, etc.
14	0	138	138	14" pipe had been Broken and stopped at 138'
12"	138	460	322	12" pipe was Broken at 460' we Repaired pipe
10"	460	520.	60	with a sleeve, it was solid to 460.
				10" Casing was run to Bottom of well.

GENERAL INFORMATION—Pumping Test, or Boiling Test, Quality of Water, etc.

Well was equipped with 200' setting 6" Turbine pump. delivers 250 gpm.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed Dave McNeech
Well Driller

By Dave McNeech

License No. 219.

Dated Sept 24, 1968.

(Not to be filled in by Driller)