WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 56619
Rec. 19
Well No. .....
Permit No. 15301
Do not fill in

Owner Charles [redacted] Driller S. R. McKinney & Son

Address R. R. 1, Sunset rd. Las Vegas, Nev Address 1042 S. Main, Las Vegas Lic No. 45

Location of well: SE¼ SE¼ Sec. 36, T. 21 N/S, R. 61 E, in Clark County

or .....

Water will be used for Domestic QM Total depth of well 107

Size of drilled hole 80 ft 12", 8" from 80 to 107 ft. Weight of casing per linear foot 28 lb.

Thickness of casing 5/16" Temp. of water .....

Diameter and length of casing 8" 85 ft.
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure Well flowing 15 G.P.M.

If nonflowing well give depth of standing water from surface .....

If flowing well describe control works Well capped with 1½HP. pump welded on top, 1½" outlet on side.
(Type and size of valve, etc.)

Date of commencement of well Aug. 1, 1952 Date of completion of well Aug 12, 1952

Type of well rig Bucyrus Erie 24 L, Spudder

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	5	5	Surface ~~xxx~~ soil
5	27	22	Grey sandy clay
27	40	13	Grey clay
40	62	22	Grey sandy clay
62	75	13	Brown clay
75	80	5	Red sandy clay water
80	95	15	Red sandy clay
95	100	5	Gravel
100	105	5	Gravel, Water
105	107	2	Red sandy clay

Water-bearing Formation, Casing Perforations, Etc.

Chief aquifer (water-bearing formation)

from 100 to ~~to~~ 107 ft.

Other aquifers .....

First water at 75 **feet.**

Casing perforated

from ..... to ..... ft.

Size of perforations .....

(OVER)

LOG OF FORMATIONS—*Continued*

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.
8" I.D.	0	85	85	Cemented hole with 4 yds. cement.
				Well flowing broke into old well which only had 20 feet of Casing in it, when both wells were shut in water came up around garage in which old well was situated. Pumped 132 sacks of cement down new hole and shut off flow in old well, then drilled out cement in new well.

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

Bailed 50 G.P.M. lowered water level to 35 feet.

WELL DRILLERS STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed [signature]
Well Driller

By

License No. 45

Dated 8-18, 1952

(Not to be filled in by Driller)