WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

Log No. 3119
Rec. 08/15/1955
Well No.
Permit No. 11327
Do not fill in

LOG
AFTER CLEAN OUT

Owner T. A. Walls Driller S. R. McKinney & Son

Address Paradise Road, Las Vegas, Nev. Address 1042 S. Main Las Vegas Lic. No. 45

Location of well: SW ¼ SW ¼ Sec. 15 T 21 N/S, R 61 E, in Clark County

or

Water will be used for D. & I. Total depth of well Cleaned out to 630

Size of drilled hole Weight of casing per linear foot 26 lb. 6" liner

Thickness of casing 1/4" Temp. of water Ran 6-5/8" O.D. liner

Diameter and length of casing Found 10" to 32 ft., 8" O.D. from 0 to 338, from 210 to 606 ft.
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure

If nonflowing well give depth of standing water from surface Water level raised from 45 ft. to 19 ft. after cleaning out to 630 ft.

If flowing well describe control works
(Type and size of valve, etc.)

Date of commencement of well July 26, 1955 Date of completion of well August 13, 1955

Type of well rig Bucyrus Erie 24 L, Spudder

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material

Water-bearing Formation, Casing Perforations, Etc.

Chief aquifer (water-bearing formation)

from ..... to ..... ft.

Other aquifers Water level raised at aprox. 600 ft. level was being cleaned out.

First water at ..... feet.

6" Casing perforated
from 210 to 606 ft.

Size of perforations
3/16" X 10"

Dw 4-5767

(OVER)

919

LOG OF FORMATIONS—*Continued*

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.
6" I.D.	210	606	606	Moved on well which was contaminated, drilled out cement and drilled 3, 8" holed alongside of 10" and 8" pipe to 110 feet in depth, and cemented with 150 sacks of pure cement and 3 yards of 6 sack mix grout at the top. Well was cemented down approximately 15 feet when we moved our rig on.

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

Surface water encountered in drilling outside of casing had very strong cesspool smell.

Well had some 6" 12 gauge liner in it, we fished out 60 feet of liner which was rusted into.

Water was tested by Health Department and was OKd after cleanout job was completed.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed S. R. McKinney & Son
Well Driller

By M. C. McKinney

License No. 45

Dated Aug 19, 19 55

(Not to be filled in by Driller)