T&T Well Log No 3924
No 1
Sec 25 T16S, R48E

3924

1-G-4

Sec. 25

I

ROSCOE MOSS COMPANY

4360 WORTH STREET
Los Angeles, CAL.

WELL CONTRACTORS — RENTAL TOOLS

Log of Well No. 81 Driller for F. M. Jenifer
Of T. & T Ranch
Exact Location
Started Work May 21, 1921
Completed Work June 1, 1921
Total depth 203 Size of shoe
204-1/2 ft. of 16 inch 10 lb. or gauge casing used and left in Well

Type of Perforator used Mills

Perforated	ft. to	ft.	Holes per	inches
96	104	12	12	
108	110	12	12	
126	128	12	12	
132	135	12	12	
138	140	12	12	
178	181	12	12	
188	191	12	12	

Make diagram of perforations in square showing dimensions.

Diameter of Perforations 5/8
Length of Perforations 3-1/2
Depth at which water was first found 81 ft.
Standing level before perforating 72
Standing level after perforating 72 ft.
Note below your observation of any change in water level while drilling

Water level when first started Test ft.
Draw-down from standing level
No. of gallons per minute pumped when Test first started
No. of gallons per minute pumped when Test completed
Draw down at completion of Test ft.
Hours Testing Well
Formations Mention size of water gravel.

0 ft.	to 47 ft.	Sand
47	75	Cemented gravel
75	81	Sandy clay
81	83	Sand
83	96	Sandy clay
96	104	Clay and fine gravel
104	108	Sand
108	116	Gravel
116	116	Sandy clay

Log No 3924

Sec 25
No 1

116	128	Gravel
128	[illegible]	Sandy clay
132	135	Gravel
135	138	Sandy clay
138	146	Gravel
146	155	Sand[illegible]
155	166	Cemented gravel
166	176	Limestone
178	181	Gravel
181	185	Cemented gravel
185	191	Gravel
191	194	Sandy clay
194	203	Clay

If reducing strings of casing were cut off, state how cut

Depth from surface cut ..... ft.

Size of casing cut ..... in.

Lap in larger casing ..... ft.

Was adapter or cement used?

If casing was [illegible] or repaired, state depth, describe [illegible] and condition in which [illegible] was left and probable future effect.

Make drawing of casing [illegible]

Is well straight, top to bottom?

If not, what is the variation?

Will there be any detrimental effect on pump?

If so, what effect?

No. of tons of gravel installed in well

Give any additional [illegible] which may be of future value.

Driller must fill in report as work progresses and report must be complete for his successor.

Date of report June 1, 1921

F. V. Kelley

Driller

Type and Rig No. used