STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 124480
Permit No.
Basin 089

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67293
WELL NAME (*if applicable*):

1 OWNER Greg & Debra Hunyada
MAILING ADDRESS 10739 E. Bennett Rd.

ADDRESS AT WELL LOCATION 2375 Brenda Way
Washoe Valley, NV 89704
Subdivision Name New Washoe City 83 County: Washoe

2 LOCATION NW ¼ NE ¼ Sec 31 T 17N N/S R 20 E
PERMIT/WAIVER No R-903 (Issued by Water Resources) 050-381-16 (Parcel No.)

Latitude 39.2993
Longitude 119.7773
UTM E
N
☐ NAD 27 ☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? Yes
If yes, what is replacement well NO? 74649

Is there an existing well log? Yes
If yes, what is NDWR well log #? 44310

4 EXISTING WELL CONSTRUCTION
Depth Drilled 226 Feet Depth Cased 226 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 1/8		.188	+1	130
5		.188	45	226

Existing Perforations:
Type of perforation Torch & Factory
Size of perforation

From	69	feet to	103	feet
From	114	feet to	128	feet
From	161	feet to	181	feet
From	201	feet to	221	feet
From		feet to		feet

5 WATER LEVEL
Static water level 76 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments
The pump is stuck in the well. A new replacement well was drilled 10 feet from the existing well using the air method and in the process of the drilling the air blew over into the existing well and fill it from the bottom of the well to 66 feet.....

The original Well Driller's Report # 18275

Washoe County Permit # WL160004

RECEIVED 2016 FEB 29 PM 2:43 STATE ENGINEER'S OFFICE

NAD 27
39.299390
119.776282

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: Unable to remove pump, pipe or wire from well to to being stuck in the well.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: ____ feet to ____ feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforator used: None

From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		
From		feet to		feet	Number of perfs per linear foot		

8 WELL PLUGGING MATERIALS

					Material Used		
From	0	feet to	20	feet	Neat Cement	☒ Pumped	☐ Poured
From	20	feet to	66	feet	Bentonite	☒ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight 15 lbs/gal
Bentonite Grout 30 % bentonite
Date Started 2/24/2016
Date Completed 2/24/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Fundin Pump & Well Service (Contractor)
Address 4030 Eastlake Blvd. (Contractor)
Washoe Valley, NV 89704

Nevada contractor's license number issued by the State Contractor's Board 74720
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2205
Signed (By driller performing actual drilling on site or contractor)
Date 2/26/2016

USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

Plugging well log 44310