

WELL LOG AND REPORT TO THE STATE ENGINEER OF NEVADA

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY

Log No. <u>5526</u>
Rec. <u>Nov. 7</u> 19 <u>60</u>
Well No. _____
Permit No. _____

Do not fill in

Owner L. A. Hughes Driller Wayne Burroughs

Address 3655 Le May Lane Reno, Nevada Address 2171 East Second St. Lic. No. 257

Location of well: 1/4 SE 1/4 Sec. 12, T. 18 N/S, R. 18 E, in _____ County
or _____

Water will be used for domestic Total depth of well 220'

Size of drilled hole 8" Weight of casing per linear foot _____

Thickness of casing 12 Gauge Temp. of water cold

Diameter and length of casing 8" - 204'
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure _____

If nonflowing well give depth of standing water from surface 160'

If flowing well describe control works _____
(Type and size of valve, etc.)

Date of commencement of well 10-1-59 Date of completion of well 10-18-59

Type of well rig Cable rig

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	45	45	Boulders
45	55	10	Hardpan
55	170	115	Clay
170	220	50	Gravel Water

Water-bearing Formation, Casing Perforations, Etc.

Chief aquifer (water-bearing formation)

from 180 to 215 ft.

Other aquifers _____

First water at 170 feet.

Casing perforated

from 170 to 202 ft.

Size of perforations

1/4 X 4

LOG OF FORMATIONS—Continued

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	"Remarks"—Seals, Grouting, Etc.

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

After well was drilled, customer called to have us install a pump, but due to previous committments, we were unable to give immediate service, so he called in another firm. Customer complained the well was not delivering sufficient water so although no guarantee as to output had been made by us, Burroughs Elect. volunteered to move the rig in at no charge and check the well. Customer preferred to have another firm check the well - then later asked Burroughs Electric to check same, which we did. In checking our findings indicated that well had been filled back to approximately 200 feet with Gravel, which customer stated had been thrown in by other firm, but would give no reason why. Burroughs Electric drilled well back to original 220' and requested Customer to measure with Driller, which he refused to or have well drilled deeper in order to obtain more water. At this point Drilling Rig was removed from customers Property.

WELL DRILLER'S STATEMENT
(Not to be filled in by Driller)

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed

Walter Burroughs
Well Driller

By

License No.

Dated....., 19.....

1960 NOV 7 AM 11 01

STATE ENGINEER
OFFICE