



THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. <u>18119</u>		JOB NAME: <u>LV Paving</u>			
DATE STARTED <u>12-10-09</u>	DATE COMPLETED	LOGGED BY <u>Ed</u>	DRILLED BY <u>Ed</u>	TYPE OF DRILL RIG <u>#31</u>	JOB NO. <u>5970</u>
DEPTH OF HOLE <u>40'</u>	DIAMETER OF HOLE <u>24"</u>	CASING <u>8"</u>	PERFORATIONS <u>20'</u>	SAMPLING METHOD	ELEVATION


LOCATION

409+00 To 408+50

DRILLERS NOTES:

DEPTH	SAMPLES	GRAPHIC	DESCRIPTION
0'			Red silty clay
0'			Red silty sand
10'			Red silty sand
20'			
30'			
40'			cemented gravel
50'			
60'			
70'			
80'			
90'			
100'			

The red silty sand has a small binder factor to it but I couldn't feel a clay like substance in it. The red silt must be acting as a binder.



DEC 14 2009