

AMERICAN DRILLING & PUMP SERVICE

2 of 2

Log # 112147

3040 CALAHAN STREET
WINNEMUCCA, NV 89445

PHONE: 775-623-2465
FAX: 775-623-4410

To Whom It May Concern:

Attached is the corrected log requested by the division. I apologize for the late return of this log. I was not aware that the original log had not been turned in. The first log received by the division of water resources was from the customer. The log that I gave the customer was one that I hastily put together from my notes. I made several mistakes in filling out that log. My intent was mainly to provide a lithology so that she could have information to deepen the well. I was not trying to deceive anyone.

The well referred to in this log, as you are aware, has gone dry. This well was not a good one that went bad but rather a marginal one that got worse. You will note in the log that a flow rate is not filled in. The reason for this is that a continuous flow could not be established by airlifting or by subsequent pumping. Two days were spent back flushing with water and dispersants to get a modest yield. A pump system was installed to accommodate the low yield of the well. The customer had adequate flow for household use, but could easily draw down the well with a garden hose. The customer accepted the well in this condition and did not want to undergo the expense and risk of deepening the well at the time of completion.

Sincerely,

Owen Brinkerhoff



STATE OF NEVADA
2010 NOV 14 5 11 PM '05