

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 122591
Permit No. 49950
Basin CB1

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 73708
WELL NAME (if applicable): PW-8

1 OWNER Newmont Gold Company
MAILING ADDRESS 1655 Mountain City Hwy
Elko NV 89801

ADDRESS AT WELL LOCATION Newmont Carlin
Subdivision Name: Gold Quarry County: Elko

2 LOCATION 1/4 SE 1/4 Sec 26 T 34 N R 57 E
PERMIT/WAIVER No. 49950

Latitude _____ UTM E 567178N NAD 27
Longitude _____ N 4517287 NAD 83WGS 8

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
Is there an existing well log? NO
If yes, what is replacement well NOI? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 576 Feet Depth Cased 576 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>12 3/4</u>	<u>Production Casing</u>	<u>0</u>	<u>0</u>	<u>576</u>

If well was not cleaned out to total depth, please explain why:
Pump stuck in casing well went dry Newmont tried pulling pump

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: _____ feet to _____ feet
Was the casing over drilled? yes no

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	To	feet
<u>156</u>	<u>milled</u>	<u>3" x 1/8"</u>		<u>576</u>	

Additional Perforations:

From	Type of perforator used:	feet to	feet	Number of perfs per linear foot
<u>None</u>				

5 WATER LEVEL
Static water level Dry feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Column pipe and production casing left in hole.
Trimmed in neat cement till it came to surface.
Abandoned hole per process described by Bob St. Louis and approved by Hamilton Reed. I have included a copy of that letter.

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Material	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>576</u>	<u>0</u>	<u>feet</u>	<u>neat cement</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 9.7 (lb/gal)
Bentonite Grout _____ % bentonite

Date Started 8-4-15
Date Completed 8-5-15

plug well log 25879
tab 27
40,503691
11/16/202673
3,400 gallons of cement used

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Nevada
Address P.O. Box 2748
Elko NV 89803
Nevada contractor's license number _____
issued by the State Contractor's Board 0021978
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2396
Signed Fermin Luna
Date 8-5-15

RECEIVED
 2015 AUG 17 PM 12:19
 ENGINEERS OFFICE

RECEIVED

AUG 13 2015

STATE ENGINEER'S OFFICE
ELKO OFFICE