

State of Nevada

Division of Water Resources

Attachment to Well Driller's Report

NOI 74480 Original Well Driller's Report Log #70840

On or about July 30, 2014 Boart Longyear Pump Division employees began the process of cleaning out and installing an 8" liner in Well # 1 at Scorpio Gold, Mineral Ridge Mine. During this process a 7" collar with an 8-1/2" bit was used to grind up various materials that were lodged in this well. These materials consisted of stainless steel banding, transducer cable, wood, PVC and chunks of rubber. After removing as much of this material as possible an 8" liner was installed to 1729.07' of the well. The well was then flushed with clean water and acid treated. When the ph was brought down to 5.8 the mine determined that was good and the drill pipe was tripped out. On September 2, 2014 the pump equipment was reinstalled and the well was placed back into service.

DCNR/DWR/SNBO
RECEIVED
NOV 25 2015