

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 114546
Permit No. 64577
Basin 21A

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36002

1 OWNER C-T-1 LLC ADDRESS AT WELL LOCATION 7204 W. CRAIG RD.
MAILING ADDRESS 4375 POLARIS AVE. #4 LAS VEGAS, NV 89129
LAS VEGAS, NV 89103 Subdivision Name: _____ County: _____

2 LOCATION SE 1/4 NW 1/4 Sec 3 T 20S N/S R 60 E Latitude N36 04' 28.01"N UTM E NAD 27
PERMIT/WAIVER No. 64577 138-03-201-009 Longitude 115 15' 11.6"W N NAD 83/WGS 84
10883 Issued by Water Resources Parcel No. _____

3 Comm TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes
If yes, what is replacement well NOI? 36001 If there is an existing well log? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled _____ Feet Depth Cased _____ Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8			+1.5	?

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet

5 WATER LEVEL
Static water level 164 feet below land surface
Artesian flow no G.P.M. _____ P.S.I. _____
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Perforator stopped at 25' due to very heavy scale buildup.
Run 7-7/8" dia. drill bit to clean out rust and to refusal at 280'.
Great difficulty extracting drill bit out of well due to steel casing collapsing on drill pipe.
Hole collapsed from 280' to 164'.
Obtained waiver for not perforating R1535.
Run trimmie pipe to 164' and pumped 15 yards of neat cement to surface. The 300% of overage of cement was due to the cement finding its way thru the collapses well to the bottom portion of the well.

**DCNR/DWR
RECEIVED**

OCT 31 2011

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why:
Drilled out to 280' well collapsed to 164'

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: none

From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0	feet to	164+	Neat cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 17-Oct-11
Date Completed 20-Oct-11

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name ALLEN DRILLING INC Contractor
Address 4015 WEST TOMPKINS AVE Contractor
LAS VEGAS, NV 89103
Nevada contractor's license number issued by the State Contractor's Board 18916 & 18917
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1376
Signed [Signature] By driller performing actual drilling on site or contractor
Date 25-Oct-11