

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 15231  
Permit No. 716867  
Basin 137B

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67563

1. OWNER Round Mountain Gold Corp. DW48 ADDRESS AT WELL LOCATION Round Mountain Mine  
MAILING ADDRESS PO Box 480 Round Mountain, NV 89045 Round Mountain, NV 89045 Subdivision Name: County: Nye

2. LOCATION SE 1/4 NE 1/4 Sec 30 T10N/ R44E Latitude 4283186  NAD 27  
PERMIT/WAIVER NO. R-682 Longitude N 0493375  NAD 83/WGS 84  
*Issued by Water Resources* Parcel No.

3. TYPE OF WELL  Domestic  Municipal/Industrial  Irrigation  Monitor  Test  Stock  
Is this well being plugged because a replacement well was drilled?  Yes  No  
If yes, what is replacement well NOI? 95852  
Is there an existing well log?  Yes  No  
If yes, what is NDWR well log #? 95852

4. EXISTING WELL CONSTRUCTION  
Depth Drilled 800 Feet Depth Cased 750 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
12.750	49.56	.375	+2	603

Existing Perforations:  
Type of perforation Wire wrap  
Size of perforation .125  
From 3 feet to 43 feet  
From 143 feet to 183 feet  
From 323 feet to 603 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

5. WATER LEVEL  
Static water level: N/A feet below land surface  
Artesian flow: \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.

Water Temperature: \_\_\_\_\_ °F Quality \_\_\_\_\_

6. Additional Notes or Comments  
**Well was mined off 147' previously.  
Therefore, the current screened intervals do not match  
well log 95852.**

**Materials used 500 cu. ft. neat cement**

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  Yes  No  
If well was not cleaned out to total depth, please explain why:  
**Pump and column stuck in well**

Was the well contaminated?  Yes  No  
Was the casing pulled?  Yes  No  
Was the casing over drilled?  Yes  No  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

8. WELL PLUGGING MATERIALS  
Material Used  
**Neat**  
From 0 feet to 603 feet **ceMENT**  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started September 6, 2011  
Date Completed September 7, 2011

9. DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Boart Longyear Drilling  
(CONTRACTOR)  
Address 2745 California Ave.  
(CONTRACTOR)  
Salt Lake City, UT 84104  
Nevada contractor's license number issued by the State Contractor's Board 0021976  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2239  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date September 14, 2011

RECEIVED  
2011 SEP 22 AM 11:27  
STATE ENGINEER'S OFFICE