

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 118138  
Permit No. \_\_\_\_\_  
Basin 21a

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37747

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [ Nellis A.F.B. ]  
MAILING ADDRESS Washington DC

Subdivision Name: \_\_\_\_\_ County: Clark  
2 LOCATION NW ¼ NE ¼ Sec 10 T 20S N/S R 62 E Latitude 36.232316 UTM E  NAD 27  
PERMIT/WAIVER No. H-000078 140-10-101-001 Longitude 115.030826 N  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? no  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 87 Feet Depth Cased 87 Feet  
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>pvc</u>	<u>40sch</u>	<u>0</u>	<u>87</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Existing Perforations:  
Type of perforation Factory  
Size of perforation 0.02

From	feet to	feet	feet
<u>57</u>	<u>87</u>		

Type of perforator used: try to pull casing and knocked out bottom

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 46 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments  
try to pull casing  
knocked out bottom  
**DCNR/DWR/SNBC**  
**RECEIVED**  
**SEP 17 2013**  
tremied  
filled from botton  
to top  
3961302 28mw-107

Material Used

From	feet to	feet	Material	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>20</u>	<u>87</u>	<u>feet</u>	<u>quik grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<u>0</u>	<u>20</u>	<u>feet</u>	<u>concrete mix</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/17/2013  
Date Completed 8/17/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC.  
Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119  
Contractor  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 8/21/2013