

**OFFICE OF THE STATE ENGINEER  
OF THE STATE OF NEVADA**

IN THE MATTER OF APPLICATION FOR        )  
A WELL DRILLER'S LICENSE FILED BY        )  
GLENN ROBB.                                    )

**RULING**

**# 5961**

**FINDING OF FACT**

An application for a Nevada Well Driller's License was filed by Glenn Robb in the office of the State Engineer on March 10, 2008, together with the statutory filing fee.<sup>1</sup>

Requests for four references were mailed on March 10, 2008. Responses were received from three of the requests. The Applicant was notified March 26, 2008, to appear before the Statewide Well Drillers' Advisory Board on May 2, 2008, at 8:00 a.m. in Las Vegas, Nevada. The applicant canceled this appointment by phone.<sup>2</sup>

The Applicant was notified on July 15, 2008, by certified mail to appear before the Statewide Well Drillers' Advisory Board on August 14, 2008, at 8:00 a.m. in Las Vegas. The applicant failed on Part I of the written examination with a score of 65, a score of 70 is passing.<sup>3</sup>

The Applicant was notified on October 15, 2008, by certified mail to appear before the Statewide Well Drillers' Advisory Board on November 14, 2008, at 8:00 a.m. in Las Vegas. The applicant passed Part I of the written examination with a score of 77 and passed Part II of the examination, identification of a well location on a map, however, based upon the applicant's responses to questions regarding drilling equipment and drilling practices during Part III of the examination the applicant failed to demonstrate sufficient knowledge and experience as a well driller.<sup>4</sup>

The Applicant was notified on January 7, 2009, by certified mail to appear before the Statewide Well Drillers' Advisory Board on February 6, 2009, at 8:00 a.m. in Las Vegas. The applicant did not appear as requested and did not notify the Office of the State Engineer that he would not appear.<sup>5</sup> The Statewide Well Drillers' Advisory Board recommended denial of the application of Glenn Robb on February 6, 2009.

---

<sup>1</sup> Well Driller License file is public record in the office of the State Engineer.

<sup>2</sup> Statewide Well Drillers' Advisory Board minutes of Meeting 2-2008, May 2, 2008, filed in well driller license file.

<sup>3</sup> Statewide Well Drillers' Advisory Board minutes of Meeting 3-2008, August 14, 2008, filed in well driller license file.

<sup>4</sup> Statewide Well Drillers' Advisory Board minutes of Meeting 4-2008, November 14, 2008 filed in well driller license file.

<sup>5</sup> Statewide Well Drillers' Advisory Board minutes of Meeting 1-2009, February 6, 2009, filed in well driller license file.


**CONCLUSION**

The State Engineer concludes that the Applicant failed to pass all three portions of the examination as required in the NAC § 534.282 (1) (g), (2) (b) and NAC § 534.286.

**RULING**

The State Engineer concurs with the recommendation of the Statewide Well Driller's Advisory Board and the application of Glenn Robb is herewith denied on the grounds that the Applicant failed to substantiate his experience and ability as a water well driller.

Respectfully submitted,

  
Tracy Taylor, P.E.  
State Engineer

TT/sg

Dated this 25th day

of February, 2009.