



STATE OF IDAHO  
 COUNTY OF TWIN FALLS / SS

I, Charles D. Howard, being first duly sworn, depose and say that this map has been correctly drawn to the designated scale from field notes of a survey made under my supervision and direction, between the 5<sup>th</sup> day of November, and the 6<sup>th</sup> day of November, 1979; that it truly and correctly represents the proposed location and extent of the works used to divert water from an underground source, in Washoe county, by David Facer

for irrigation purposes. That the proposed point of diversion, the approximate location and size of the diverting channel, all reservoirs or basins, the location and names of all other works which will cross or connect with the proposed works, and the boundary of all lands, showing by 40-acre subdivisions the areas proposed to be irrigated, are fully and correctly designated thereon.

*Charles D. Howard*  
 13 Nov 1979

State Water Right Surveyor #535

Subscribed and sworn to before me  
 this 13<sup>th</sup> day of November, 1979.  
 Notary Public in and for Twin Falls County, Idaho.

*Kathy Eiler*



SCALE: 1" = 1000'

**FILED**  
 Nov. 29, 1979  
 STATE ENGINEER'S OFFICE

NOV 29 PM 2 29

**ENM** Edwards, Howard & Marston, Inc. TWIN FALLS, IDAHO  
 ENGINEERS - PLANNERS - SURVEYORS PH. 1-208-734-6888

**MAP**  
 To Accompany Application to Appropriate Water for Irrigation  
 By David Facer from an Underground Source  
 Application Number 38055

**38055**

UNSURVEYED

T. 33 N. 34 35 S 89° 59' 44" W 2640.45' (mea.) 35 36 DUE WEST - BASE BEARING G.L.O. 2639.15' (mea.) 2 1 2639.15' (mea.) 1 6 2639.87' (mea.) 31 32 S 89° 58' 40" E 2639.87' (mea.) 6 5 T. 33 N.  
 T. 32 N. 3 2 2640.45' (mea.) 2639.15' (mea.) 2 1 2639.15' (mea.) 1 6 2639.87' (mea.) 31 32 T. 32 N.

R. 69 E. 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 R. 70 E. 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

**LEGEND**

- Township Line
- Section Line
- 1/4 Line
- 1/16 Line
- - - - - Place of Use
- ◇ Section Corner Found U.S.G.L.O. Brass Cap
- ◆ 1/4 Corner Found U.S.G.L.O. Brass Cap
- Corner Not Found
- Corner Unsurveyed - Protracted

NOTE! All Distances are Record as Provided by Government Land Office Unless Otherwise Shown.  
 Base Bearing - as Shown (True Bearing) North Line  
 Section 1, T. 32 N. R. 69 E., M.D. B. & M.