

**WELL LOG AND REPORT TO THE STATE ENGINEER
OF NEVADA**

Log No. 95-87
 Rec. July 12 1967
 Well No. _____
 Permit No. _____

Do not fill in.

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY

Owner Bureau of Land Management Driller Frank J. Schuh

Address Pioche Star Route, Ely, Nevada 89301 Address Box 745, Ely, Nevada Lic. No. 382

Location of well: SE 1/4 SW 1/4 Sec. 35, T. 9 N/S, R. 59 E, in Nye County

Permit No. _____

Water will be used for Stock Water Total depth of well 160

Size of drilled hole 9 in. Weight of casing per linear foot none

Thickness of casing None Temp. of water _____

Diameter and length of casing _____
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)

If flowing well give flow in c.f.s. or g.p.m. and pressure _____

If nonflowing well give depth of standing water from surface _____

If flowing well describe control works _____
(Type and size of valve, etc.)

Date of commencement of well 5/25/67 Date of completion of well 6/7/67

Type of well rig Cable Tool

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material
0	5	5	Surface
5	30	25	Clay and Sand
30	40	10	Gravel
40	60	20	Brown Clay
60	160	100	Black Shale

Water-bearing Formation, Casing Perforations, etc.

Chief aquifer (water-bearing formation)

from _____ to _____ ft.

Other aquifers _____

Dry Hole

First water at None feet.

Casing perforated

from none to 0 ft.

Size of perforations

None

log# 89361 File with Log
9587

IN REPLY REFER TO:



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT



1100

Ely District Office
Pioche Star Route
Ely, Nevada 89301

August 1, 1967

State of Nevada
Department of Conservation & Natural Resources
Division of Water Resources
201 South Fall Street
Carson City, Nevada 89701

Gentlemen:

Reference is made to your letter dated July 13, 1967, concerning a dry hole we drilled in the SE $\frac{1}{4}$ SW $\frac{1}{4}$, Section 35, T. 9 N., R. 59 E., M.D.B. & M.

The well was plugged with rocks upon abandonment. I am sorry we neglected to put this information on the well log. We will do so on future logs.

Sincerely yours,

Roy W. Bean
District Manager