

**WELL LOG AND REPORT TO THE STATE ENGINEER
OF NEVADA**

Log No. 7305
 Rec. July 30 1963
 Well No. _____
 Permit No. _____

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY

Do not fill in.

Owner Meadow Valley Ranches Driller A. O. Large
 Address P.O. Box 702 Stockman Mts Address Box 845, Eeko Lic. No. 397
 Location of well: $\frac{1}{4}$ $\frac{1}{4}$ Sec. 35, T35 N $\frac{1}{4}$, R 55 E, in Eeko County
 or Block 61 Lot 5
 Water will be used for Test Well Total depth of well 152 ft
 Size of drilled hole 4 1/4 Weight of casing per linear foot None
 Thickness of casing None Temp. of water None
 Diameter and length of casing None
(Casing 12" in diameter and under give inside diameter; casing 12" in diameter give outside diameter.)
 If flowing well give flow in c.f.s. or g.p.m. and pressure _____
 If nonflowing well give depth of standing water from surface _____
 If flowing well describe control works _____
(Type and size of valve, etc.)
 Date of commencement of well 7-2-63 Date of completion of well 7-12-63
 Type of well rig Porter Drill Rotary

LOG OF FORMATIONS

From feet	To feet	Thickness feet	Type of material	Water-bearing Formation, Casing Perforations, etc.
<u>Top</u>	<u>18</u>	<u>18</u>	<u>Light Brown sandy loam mixed with sand & boulders</u>	Chief aquifer (water-bearing formation) from <u>None</u> to <u>None</u> ft.
<u>18</u>	<u>152</u>	<u>134</u>	<u>Light Brown clay no indications of water no sand or gravel to 152 ft.</u>	Other aquifers _____ First water at <u>None</u> feet. Casing perforated from <u>None</u> to <u>None</u> ft. Size of perforations <u>None</u>

LOG OF FORMATIONS—Continued

From feet	To feet	Thickness	Type of material

CASING RECORD

Diam. casing	From feet	To feet	Length	REMARKS—Seals, Grouting, etc.

GENERAL INFORMATION—Pumping Test, Quality of Water, etc.

WELL DRILLER'S STATEMENT

This well was drilled under my jurisdiction and the above information is true to my best information and belief.

Signed *[Signature]*
Well Driller

By.....

License No. 397

Dated 7-27, 1963

(Not to be filled in by Driller)

1963 JUL 30 AM 10 03

STATE ENGINEER
OFFICE