

WELL DRILLER'S REPORT

Please complete this form in its entirety

OFFICE USE ONLY
Log No. 315223
Permit No. 13-212
Basin 13-212

NOTICE OF INTENT NO. 1

1. OWNER NEVADA AIR FORCE BASE
MAILING ADDRESS _____

ADDRESS AT WELL LOCATION WASTE PUL. STORAGE AREA - FACILITY 1014 - HW129

2. LOCATION SE 1/4, SE 1/4 Sec 33 T 19 N R 62 @ CLARK County
PERMIT NO. W10-126a Issued by Water Resources Parcel No. _____ Subdivision Name _____

3. TYPE OF WORK
New Well Recondition Other
Deepen Domestic Municipal
PROPOSED USE
Irrigation Industrial Test Stock
5. TYPE WELL
Cable Rotary Other ROTARY STEEL TUBER

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thickness
SANDY SILT		0	5	5'
SILT		5	40	35'
SANDY SILT		40	50	10'
SAND		50	60	10'
SANDY SILT		60	70	10'
SILT		70	102	32'

Date started FEBRUARY 22, 1981
Date completed FEBRUARY 22, 1981

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump
	<u>67.67</u>	<u>7'-11M</u>	<u>68.</u>

BAILER TEST
G.P.M. _____ Draw down _____ feet _____ hours
G.P.M. _____ Draw down _____ feet _____ hours
G.P.M. _____ Draw down _____ feet _____ hours

8. WELL CONSTRUCTION
Diameter 8 inches Total depth 102 feet
Casing record PVC WELLS CASING
Weight per foot _____ Thickness _____

Perforations:
Type perforation SPOTTED SCREEN
Size perforation .020 IN
From 101.5 feet to 71.5 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

9. WATER LEVEL
Static water level 83.5 feet below land surface
Flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.
Name AF Drilling, Inc.
Address 1450 B. St Manhattan Contractor
Fullerton, 92603 Contractor
Nevada contractor's license number _____
Issued by the State Contractor's Board
Nevada contractor's driller's number _____
Issued by the Division of Water Resources
Nevada driller's license number issued by the Nevada Division of Water Resources, the on-site driller
Signed [Signature] 10/14
Date 5/3/89
By driller performing actual drilling on site or contractor