



888 Cooper
Overton, Nevada 89040
Telephone (702) 397-2022

Log# 43670
Permit# 17749
Basin# 13-205



October 8, 1990

Local No S12E6512 ba
Completion Date: 4-19-1990

Department of Conservation and Natural Resources
Division of Water Resources
Capitol Complex
123 W. Nye Lane
Carson City, NV 89710

RE: Incomplete Well Logs

Attn: Michael J. Anderson, Hydraulic Engineer I

Dear Mr. Anderson:

In response to your letter of September 13th and after reviewing my original logs for the C.P. Breedlove well, I submit the following information.

The #3 well is a replacement well. I erroneously neglected to file a plugging report for the abandoned well. The abandoned well was plugged to 65 feet with cement grout. The errors on the well drillers report were due to typographical errors by my secretary. I apologize for the sloppy paper work and will review reports more closely before signing and submitting.

The well was sealed to 50 feet and perforations were from 86 to 106 feet. (corrected report is attached also copy of contract and original log).

Respectfully,
Bud Webber

L. R. 'Bud' Webber Driller# 1557

Enclosures: 3

Plugging of log # 6900
Permit 17749
1RR