



STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY 102327  
Log No. ....  
Permit No. ....  
Basin .....

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 58853

1. OWNER Newmont Mining Corporation **WW-33** ADDRESS AT WELL LOCATION Lonetree Minesite  
Box 388  
MAILING ADDRESS Valmy, NV. 89438 West of Valmy, NV. 89438  
Subdivision Name: N/A County: Humboldt

2. LOCATION NE 1/4 NE 1/4 Sec 14 T34N R42E Latitude 40° 49' 38.0" N UTM E  NAD 27  
PERMIT/WAIVER NO. 59245 N/A Longitude 117° 17' 26.0" W  NAD 83/WGS 84  
Issued by Water Resources Parcel No. N/A

3. TYPE OF WELL Is this well being plugged because a replacement well was drilled?  Yes  No Is there an existing well log?  Yes  No  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? **NOI 57209**  
If yes, what is NDWR well log #?

4. EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
<b>EXISTING CASING SCHEDULE</b>			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet) To (Feet)
24	94.62	0.375	0 to 16
16	62.58	0.375	0 to 400

Existing Perforations:  
Type of perforation Louvered  
Size of perforation 0.125'  
From 60 feet to 400 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

5. WATER LEVEL  
Static water level: 15 feet below land surface  
Artesian flow: \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water Temperature: \_\_\_\_\_ °F Quality \_\_\_\_\_

6. Additional Notes or Comments  
**16" well casing tagged at 340' below ground surface. Casing had been previously mined off.**  
Materials used:  
**Abantonite: 550.8 cu. ft.**  
**3/8 hole plug: 17.5 cu. ft.**  
**Neat cement: 56 cu. ft.**

40.827222° N  
117.207222° W NAD27

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  Yes  No  
If well was not cleaned out to total depth, please explain why:

Was the well contaminated?  Yes  No  
Was the casing pulled?  Yes  No  
Was the casing over drilled?  Yes  No  
If casing was left in place, show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: N/A

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

8. WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	
From <u>50</u>	feet to <u>340</u>	feet	<b>Abantonite</b>	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From <u>45</u>	feet to <u>50</u>	feet	<b>3/8 hole plug</b>	<input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured
From <u>0</u>	feet to <u>45</u>	feet	<b>Neat cement</b>	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From _____	feet to _____	feet		<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight 15.6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 11-21-06  
Date Completed 11-21-06

9. DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Lang Exploratory Drilling (CONTRACTOR)  
Address 3707 Manzanita (CONTRACTOR)  
Elko, NV. 89801  
Nevada contractor's license number issued by the State Contractor's Board 0021976  
Nevada driller's license number issued by the Division of Water Resources the on-site driller 2047  
Signed [Signature] 11-28-06

*AW*