

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 103372
 Permit No. 51573
 Basin 161



PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 31251

1. OWNER United States Air Force Well 1 ADDRESS AT WELL LOCATION Creech AFB
 MAILING ADDRESS PO Box 569
Indian Springs, NV. 89048 Indian Springs, NV.
 Subdivision Name: N/A County: Clark

2. LOCATION SE 1/4 SE 1/4 Sec 5 T16 /S R56E Latitude 36° 34.851" N UTM E NAD 27
 PERMIT/WAIVER NO. 51573 059-05-000-00/p Longitude W 115° 40.498" N NAD 83/WGS 84
 Issued by Water Resources Parcel No. N/A

3. TYPE OF WELL Is this well being plugged because a Is there an existing well log? Yes No
 Domestic Irrigation Test replacement well was drilled? Yes No
 Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? 21076 If yes, what is NDWR well log #? 26775

4. EXISTING WELL CONSTRUCTION
 Depth Drilled 563 Feet Depth Cased 299 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8		0.250	0	299

Existing Perforations:
 Type of perforation None
 Size of perforation _____
 From _____ feet to _____ feet
 From _____ feet to _____ feet
 From _____ feet to _____ feet
 From _____ feet to _____ feet

5. WATER LEVEL
 Static water level: 41 feet below land surface
 Artesian flow: N/A G.P.M. N/A P.S.I.

Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
Notes:

Believe well to be drilled by cable tool rig. No existing well report.

Video log of well shows no existing perforations from 0' - 299', where casing ends. Open hole from 299' to 563'.

Materials used:
 Abantoni - 1,735 gallons
 Neat cement - 107 cu.

Orig log = 26775

DO NOT
 RECEIVED

JUL 02 2007

LAS VEGAS OFFICE

7. WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? Yes No
 If well was not cleaned out to total depth, please explain why: 08E

Was the well contaminated? Yes No
 Was the casing pulled? Yes No
 Was the casing over drilled? Yes No

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:

Type of perforator used: Holte

From	feet to	feet	Number of perfs per linear foot	
0	feet to	120	feet	Number of perfs per linear foot <u>29</u>
120	feet to	299	feet	Number of perfs per linear foot <u>19</u>
	feet to		feet	Number of perfs per linear foot
	feet to		feet	Number of perfs per linear foot
	feet to		feet	Number of perfs per linear foot
	feet to		feet	Number of perfs per linear foot

8. WELL PLUGGING MATERIALS

Material Used			
From	0	feet to	100
			feet
			Neat cement <input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	100	feet to	563
			feet
			Abantoni te <input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to	
			feet
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to	
			feet
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to	
			feet
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight 15.6 lbs/gal
 Bentonite Grout 20 % bentonite

Date Started 06/16/07
 Date Completed 06/16/07

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Bort Longyear Drilling Services
 (CONTRACTOR)

Address PO 5279
 (CONTRACTOR)

Elko, NV. 89802-5279

Nevada contractor's license number issued by the State Contractor's Board 0021976

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2338

Signed [Signature]
 By driller performing actual drilling on site or contractor

Date 06/22/07

RECEIVED
 2007 JUN 28 AM 11:55
 DIVISION OF WATER RESOURCES

AW