

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 104252  
Permit No. \_\_\_\_\_  
Basin 140B

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 59826

1 OWNER New West Gold USA Inc. ADDRESS AT WELL LOCATION MW-1  
MAILING ADDRESS 1658 Cole Blvd., Building 6, Suite 210 North Umlerland Mine  
NW Lakewood, CO 80401 Subdivision Name: \_\_\_\_\_ County: Nye

2 LOCATION S41/4 S1/4 NW 1/4 Sec 18 T 13N N/S/R 46 E Latitude UTM E 513343  NAD 27  
PERMIT/WAIVER No. M/O 625 Longitude N 4312710  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  Stock  
 Municipal/Industrial  Monitor  
Is this well being plugged because a replacement well was drilled? No  
Is there an existing well log? Yes  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? 41055

4 EXISTING WELL CONSTRUCTION

Depth Drilled	<u>55</u> Feet	Depth Cased	<u>55</u> Feet
---------------	----------------	-------------	----------------

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>Sch.40</u>	<u>Sch 40</u>	<u>0</u>	<u>55</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>4" PVC triloc Sch 40 - Slot</u>	<u>0.01</u>	<u>35</u>	<u>feet to</u>	<u>55</u> feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL

Static water level 35 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used	From	feet to	feet	Neat Cement	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
	<u>55</u>	<u>feet to</u>	<u>0</u> feet		<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured

6 Additional Notes or Comments  
Poured 60 gallons neat cement.  
N 38.965136  
W 116.845989 NAD83

Neat Cement Fluid Weight 15.6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/12/2007  
Date Completed 9/12/2007

STATE ENGINEERS OFFICE  
2007 SEP 17 PM 12:59

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eklund Drilling Company Inc. Contractor  
Address PO Box 2748 Contractor  
Elko, NV 89803  
Nevada contractor's license number issued by the State Contractor's Board 0030823  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1769  
Signed Waven Hattley  
By driller performing actual drilling on site or contractor  
Date 9/13/2007

RECEIVED