

Log No. 104370
Permit No. _____
Basin 104

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 59404

1. OWNER ROAD 3 ~~HWY~~ ^{HIGHWAY} ~~DEDS~~ / NDOJ ADDRESS AT WELL LOCATION Storage Sheds, 5th St
MAILING ADDRESS P.O. Box 7086 Reno Green Over Pass
N.V. 80509

2. LOCATION SW 1/4 SE 1/4 Sec. 16 T. 15 (N) R. 20 E. Carson County
PERMIT NO. 0250 Issued by Water Resources Parcel No. Subdivision Name

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other _____

4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

5. WELL TYPE
 Cable Rotary RVC
 Air Other MUD

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
SAND		0	5	
BLACK CLAY		5	25	
SAND		25	100	
SAND & CLAY		100	145	
SAND		145	170	
CLAY & SAND		170	200	
GREEN ROCK & CLAY		200	295	
GRAY & BROWN ROCK	X	295	320	
GRAY & GREEN ROCK		320	355	
With CLAY				
GRAY & GREEN ROCK		355	400	
CLAY with some	X	400	500	
GRAVEL LAYERS				
GPS: N39.159283 W119.739861				
NAD83				
N 39.159386 W 119.738862 NAD27				
PLUGGED BY NOT # 64824 (TA)				

8. WELL CONSTRUCTION
Depth Drilled 500' Feet Depth Cased 500' Feet

HOLE DIAMETER (BIT SIZE)
From 12 3/4 Inches To 0 Feet 500' Feet
Inches Feet Feet
Inches Feet Feet

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8		188	T1	500

Perforations:
Type perforation RAFT OFF
Size perforation 3/32 x 3
From 460 feet to 500 feet
From 400 feet to 490 feet
From 300 feet to 320 feet
From _____ feet to _____ feet
From _____ feet to _____ feet

Surface Seal: Yes No Seal Type:
Depth of Seal 100' Neat Cement
Placement Method: Pumped Cement Grout
 Poured Concrete Grout

Gravel Packed: Yes No
From 500 feet to 100' feet

Date started 10-1, 2007
Date completed 10-9, 2007

7. WELL TEST DATA

TEST METHOD:	G.P.M.	Draw Down (Feet Below Static)	Time (Hours)
<input type="checkbox"/> Bailer <input type="checkbox"/> Pump <input checked="" type="checkbox"/> Air Lift	<u>200</u>		

RECEIVED
2007 OCT 22 PM 1:15
STATISTICAL

9. WATER LEVEL
Static water level 9' feet below land surface
Artesian flow _____ G.P.M. P.S.I.
Water temperature 60.1 °F Quality _____

10. DRILLER'S CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.
Name Leach Drilling Inc.
Address PO Box 599, Silver Springs,
NV 89429
Nevada contractor's license number 31841
issued by the State Contractor's Board
Nevada driller's license number issued by the 5275
Division of Water Resources, the on-site driller
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 10-16-07