

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 105082  
Permit No.  
Basin 101

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 59579

1 OWNER GARY LACA, David Pantell ADDRESS AT WELL LOCATION 1870 West Williams Ave  
MAILING ADDRESS 4700 CONRAD PLACE FALLON NV 89406  
Subdivision Name: N/A County: Churchill

2 LOCATION SW 1/4 SW 1/4 Sec 25 T 19 N R 29 E Latitude N 39° 28.582' UTM E  NAD 27  
PERMIT/WAIVER No. N/A E-000068 101-231-63 Longitude W 118° 47.720' N  NAD 83/WGS 84  
Parcel No. WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor MW 8  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? -  
Is there an existing well log? yes  
If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 25 Feet Depth Casad 25 Feet

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>sch 40</u>	<u>0</u>	<u>25</u>

Existing Perforations:  
Type of perforation slotted screened  
Size of perforation 0.010  
From 0.5 feet to 2.5 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: broke bottom cap  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 9.54 feet below land surface  
Artesian flow N/A G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature W-A-M °F Quality Mucky

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
<u>0</u>	<u>25</u>	<u>Neat cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 23.5 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11/7/08  
Date Completed 11/7/08

6 Additional Notes or Comments  
MW # 8  
WGS 84  
E-000068 tracking #  
N39.476467  
W 118.757689 NAD027

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name DALE LETMAN Contractor  
Address 520 Edison Way Contractor  
RENO NV 89502  
Nevada contractor's license number C.E. 4186 (Pezavella)  
issued by the State Contractor's Board  
Nevada driller's license number issued by the M-1976  
Division of Water Resources, the on-site driller  
Signed Dale Letman  
By driller performing actual drilling on site or contractor  
Date 1/10/08