

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY 105647

Log No. _____
Permit No. _____
Basin 101

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

Please complete this form in its entirety in accordance with NRS 524.179 and NAC 524.143

PLUGGING REPORT NO. 60652

1 OWNER ROB GOINGS ADDRESS AT WELL LOCATION 1125 DODGION LANE
MAILING ADDRESS 1175 DODGION LANE FALLON, NV 89406
Subdivision Name: _____ County: Churchill

2 LOCATION NW 1/4 SW 1/4 Sec 5 T 18N N/S R 29 E Latitude 39.452564 UTM E 348530 NAD 27
PERMIT/WAIVER No. 010-171-04 Longitude 118.760413 N 4368270 NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? YES Is there an existing well log? UNKNOWN
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
If yes, what is replacement well NOI? 60659 If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 28 Feet Depth Cased 28 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>6 5/8</u>	<u>12.9</u>	<u>.188</u>	<u>0</u>	<u>28</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From		

5 WATER LEVEL
Static water level dry feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
WELL WAS FILLED WITH HYDRATED HOLE PLUG AND CUT OFF 2 FEET BELOW GRADE.

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why:
WELL WAS DRY BUT LOCATED IN A SWAMPY AREA WHERE LAND WAS TOO SOFT TO ALLOW MACHINERY ACCESS.

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:

From	feet to	feet	Number of perfs per linear foot
From			

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From					

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout NAME? % bentonite _____
Date Started 5-Feb-08
Date Completed 5-Feb-08

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name WELSO CORP. Contractor
Address P. O. BOX 888 Contractor
FALLON, NV 89406
Nevada contractor's license number issued by the State Contractor's Board 11752
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2199
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 2/28/2008