

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY *106142*
 Log No. _____
 Permit No. _____
 Basin *761* _____
 NOTICE OF INTENT NO. **61704**

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

1. OWNER **Barrick Goldstrike** **BW-20** ADDRESS AT WELL LOCATION **Barrick Golstrike Minesite**
 MAILING ADDRESS **P.O. Box 29** **North of Carlin, Nevada**
Elko, Nevada 89803 **Subdivision Name: NA** **County: Eureka**

2. LOCATION **NW 1/4 SW 1/4 Sec 24 T36N R49E** Latitude **40.981642** UTM E **551491.6** NAD 27
NE Longitude **116.387933** N **7** NAD 83/WGS 84
 PERMIT/WAIVER NO. **55143** Parcel No. **NA**
Issued by Water Resources

3. TYPE OF WELL Is this well being plugged because a replacement well was drilled? Yes No Is there an existing well log? Yes No
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #? **39088**

4. **EXISTING WELL CONSTRUCTION**
 Depth Drilled **1930** Feet Depth Cased **1759** Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
24.0	95.0	.375	0	1759

Existing Perforations:
 Type of perforation **Wire Wrap**
 Size of perforation **.050**

From 1359	feet to	1759	feet
From	feet to		feet
From	feet to		feet
From	feet to		feet
From	feet to		feet

5. **WATER LEVEL**
 Static water level: **1605** feet below land surface
 Artesian flow: **No** G.P.M. P.S.I.
 Water Temperature: °F Quality

6. Additional Notes or Comments
Well was mined off 174' below surface.
Approximate mining level will be 630'

Abantonite was pumped while pouring hole plug

Materials Used:

Neat Cement : **460 cu.ft**
 3/8 Hole Plug : **2243 cu.ft**
 Abantonite : **1185 cu.ft**
 Native Material : **1573 cu.ft**

7. **WELL PLUGGING PROCEDURE**
 Was well cleaned out to total depth? Yes No
 If well was not cleaned out to total depth, please explain why:

Was the well contaminated? Yes No
 Was the casing pulled? Yes No
 Was the casing over drilled? Yes No

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used: **Holte**

From 560	feet to	1347	feet	Number of perfs per linear foot	60
From	feet to		feet	Number of perfs per linear foot	
From	feet to		feet	Number of perfs per linear foot	
From	feet to		feet	Number of perfs per linear foot	
From	feet to		feet	Number of perfs per linear foot	
From	feet to		feet	Number of perfs per linear foot	

8. **WELL PLUGGING MATERIALS**

		Material Used			
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From 1759	feet to	687	3/8 Plug	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From 687	feet to	511	Cement	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From 511	feet to	10	Fill Dirt	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From 10	feet to	0	Cement	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight **15.6** lbs/gal
 Bentonite Grout **15.4** % bentonite

Date Started **14-Mar-08**
 Date Completed **26-Mar-08**

9. **DRILLER'S CERTIFICATION**

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **Boart Longyear Drilling Service**
(CONTRACTOR)

Address **P.O. Box 5279**
(CONTRACTOR)
Elko, NV 89802

Nevada contractor's license number issued by the State Contractor's Board **0021976**

Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2353**

Signed *[Signature]*
 By driller performing actual drilling on site or contractor

Date **31-Mar-08**