

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY 106144

Log No. _____
Permit No. _____
Basin 72d

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **61692**

1. OWNER **Barrick Goldstrike** **BW19** ADDRESS AT WELL LOCATION **Barrick Goldstrike Minesite**
MAILING ADDRESS **P.O. Box 29** **North of Carlin, NV**
Elko, NV 89803 **Subdivision Name: NA** **County: Eureka**

2. LOCATION **SE 1/4 NW 1/4 Sec 24 T36N R49E** Latitude **40°98305044** UTM E NAD 27
PERMIT/WAIVER NO. **55142** **NA** Longitude **116°390195** N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3. TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____
Is there an existing well log? Yes No
If yes, what is NDWR well log #? **38781**

4. **EXISTING WELL CONSTRUCTION**
Depth Drilled **2038** Feet Depth Cased **1930** Feet
EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
24.0	95.0	.375	0	1930

Existing Perforations:
Type of perforation **Full Flow Louvered**
Size of perforation **.125**

From	feet to	feet
From 1490	feet to	1930 feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet

5. **WATER LEVEL**
Static water level: **1721** feet below land surface
Artesian flow: _____ G.P.M. _____ P.S.I.
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
Well was mined off 73' below surface.
Mining level will be 1003'

Abantonite was pumped while pouring hole plug.

Materials Used:
Neat Cement : 434 cu.ft
3/8 Hole Plug : 2205 cu.ft
Abantonite : 963 cu.ft
Native Material : 2962 cu.ft

N 40.983151
W 116.389265 NAD83

7. **WELL PLUGGING PROCEDURE**
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: **Holte**

From	feet to	feet	Number of perms per linear foot
From 847	feet to	1467 feet	60
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____

8. **WELL PLUGGING MATERIALS**

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From 1930	feet to	1053 feet	3/8 Plug	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From 1053	feet to	953 feet	Cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From 953	feet to	10 feet	Nat Mat'l	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From 10	feet to	0 feet	Cement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight **15.6** lbs/gal
Bentonite Grout **15.4** % bentonite

Date Started **26-Mar-08**
Date Completed **29-Mar-08**

9. **DRILLER'S CERTIFICATION**
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name **Boart Longyear Drilling Services**
(CONTRACTOR)

Address **P.O. Box 5279**
(CONTRACTOR)
Elko, NV 89802

Nevada contractor's license number issued by the State Contractor's Board **0021976**

Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2353**

Signed _____
By driller performing actual drilling on site or contractor

Date **04-01-08**

(Rev 05-06)

USE ADDITIONAL SHEETS IF NECESSARY