

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 106667
Permit No. _____
Basin 179

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 58669

1 OWNER Nevada Power ADDRESS AT WELL LOCATION Near mile marker #84 on Hwy 93
MAILING ADDRESS 705 Aultman St. Ely, NV. 89315 north of McGill, NV. And then 1/2 mile west on dirt road
Subdivision Name: _____ County: White Pine

2 LOCATION SE 1/4 NW 1/4 Sec 20 T 21N N/S R 64 E Latitude 39 40.506N UTM E NAD 27
PERMIT/WAIVER No. old #25385 Longitude 114 45.873W N NAD 83/WGS 84
Issued by Water Resources: _____ Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log?
 Domestic Irrigation Test yes yes
 Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? n/a If yes, what is NDWR well log #? 12007

4 EXISTING WELL CONSTRUCTION
Depth Drilled 200 Feet Depth Cased 200 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
16		.219	+1	200

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
	torch cut	40'		200'	
	3/8"x12"				

5 WATER LEVEL
Static water level 61' feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Conducted video of well in early spring. Found casing to have large perforations and large holes in it. Spoke with Tim Hunt and due to the well not having any gravel pack, allowed us to use a 6 sack sand mix for grout. We installed 2" tremme pipe and pumped in 15 yards of sand grout. After grout was at 20' from surface, we left set overnight and placed 20' neat cement seal from 20' to surface.

2008 AUG 15 AM 11:28
STATE ENGINEER
N 39.675177
W 114.763684 NAD 27

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: Bailed well to 197' but could not retrieve any more debris

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 200' feet to 20' feet sand mix grout Pumped Poured
From 20' feet to surface feet neat cement Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured
From _____ feet to _____ feet _____ Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/5/2008
Date Completed 8/6/2008

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Carson Pump LLC Contractor
Address P.O. Box 20159 Contractor
Carson City, NV. 89721
Nevada contractor's license number issued by the State Contractor's Board 39920A
Nevada driller's license number issued by the Division of Water Resources, the on-site driller R&P-2265
Signed _____
Date 8/12/2008