

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. **106882**
 Permit No. _____
 Basin _____

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33806

1 OWNER Clark County Aviation
 MAILING ADDRESS P. O. Box 11005, Las Vegas, NV

ADDRESS AT WELL LOCATION McCarren Airport Terminal 3
5757 Wayne Newton blvd, Las Vegas, NV

Subdivision Name: _____ County: Clark

2 LOCATION NE ¼ NE ¼ Sec 34 T 21S N/S R 61 E
 PERMIT/WAIVER No. DW 1243A 162-34-502-010
Issued by Water Resources Parcel No.

Latitude 631663 UTM E NAD 27
 Longitude 486503.2 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a
 replacement well was drilled? no
 If yes, what is replacement well NOI? _____

Is there an existing well log? yes
 If yes, what is NDWR well log #? 103323

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 51 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	20

Existing Perforations:

Type of perforation	Machine Slot
From <u>20</u> feet to <u>50</u> feet	<u>0.032</u>
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

5 WATER LEVEL
 Static water level 28' feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
Existing grade was 15' below original grade, pulled well casing, and vacuum well pack to -35 below original grade (20' below existing grade) and poured cement to 5' from the surface.
 Location # 7451

7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: Casing was removed

Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforator used: _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS

Material Used			
From <u>20</u> feet to <u>35</u> feet	Cement Grout	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From _____ feet to _____ feet	Cement Grout	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	Cement Grout	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	Cement Grout	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	Cement Grout	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	Cement Grout	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 8-20-08
 Date Completed 8-20-08

9 DRILLER'S CERTIFICATION
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Griffin Dewatering Corp. Contractor
 Address 536 E. Maitland St. Contractor
Ontario, CA 91761
 Nevada contractor's license number _____
 issued by the State Contractor's Board C-23 0031246
 Nevada driller's license number issued by the _____
 Division of Water Resources, the on-site driller M-1985
 Signed [Signature]
 By driller performing actual drilling on site or contractor
 Date 9-12-08

