

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. **106884**  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33806

1 OWNER Clark County Aviation  
MAILING ADDRESS P. O. Box 11005, Las Vegas, NV

ADDRESS AT WELL LOCATION McCarren Airport Terminal 3  
5757 Wayne Newton blvd, Las Vegas, NV

2 LOCATION NE ¼ NE ¼ Sec 34 T 21S N/S R 61 E  
PERMIT/WAIVER No. DW 1243A 162-34-502-010  
Issued by Water Resources Parcel No.

Subdivision Name: \_\_\_\_\_ County: Clark  
Latitude **63.1463** UTM E  NAD 27  
Longitude **48.65004** N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled?  no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log?  yes  
If yes, what is NDWR well log #? **103329**

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 51 Feet Depth Cased 50 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: Casing was removed

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	20

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_

Existing Perforations:

Type of perforation	Machine Slot
From 20 feet to 50 feet	0.032
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

5 WATER LEVEL  
Static water level 28' feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_


8 WELL PLUGGING MATERIALS  
Material Used  
From 20 feet to 35 feet Cement Grout  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
Existing grade was 15' below original grade, pulled well casing, and vacuum well pack to -35 below original grade (20' below existing grade) and poured cement to 5' from the surface.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started **8-19-08**  
Date Completed **8-19-08**

Location # **7453**

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.



Name Griffin Dewatering Corp. Contractor  
Address 536 E. Maitland St. Contractor  
Ontario, CA 91761  
Nevada contractor's license number issued by the State Contractor's Board C-23 0031246  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1985  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date **19-12-08**