

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. **106903**
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33819

1 OWNER Clark County Aviation
MAILING ADDRESS P. O. Box 11005, Las Vegas, NV

ADDRESS AT WELL LOCATION McCarren Airport Terminal 3
5757 Wayne Newton Blvd, Las Vegas, NV
Subdivision Name: _____ County: Clark

2 LOCATION NW ¼ NW ¼ Sec 35 T 21S N/S R 61 E
PERMIT/WAIVER No. DW-1244A 162-35-101-020
Issued by Water Resources Parcel No.

Latitude **632810.8** UTM E NAD 27
Longitude **486852.3** N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____

Is there an existing well log? yes
If yes, what is NDWR well log #? **103512**

4 EXISTING WELL CONSTRUCTION
Depth Drilled 51 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	20

Existing Perforations:

Type of perforation	Machine Slot
From 20 feet to 50 feet	0.032
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

5 WATER LEVEL
Static water level 28' feet below land surface
Artesian flow _____ G.P.M. P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
Existing grade was 15' below original grade, pulled casing and vacuum out well pack to -35 below original grade (20' below existing grade) and poured cement to 5' from surface.
Location # **7418**

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: Casing was removed

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS

From	To	Material Used	Other
20	35	Cement Grout	<input type="checkbox"/> Pumpe <input checked="" type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started **8-20-08**
Date Completed **8-20-08**

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Griffin Dewatering Corp. Contractor
Address 536 E. Maitland St. Contractor
Ontario, CA 91761

Nevada contractor's license number issued by the State Contractor's Board C-23 0031246
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1985

Signed _____
By driller performing actual drilling on site or contractor
Date **9-12-08**

