

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. **106914**  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33819

1 OWNER Clark County Aviation ADDRESS AT WELL LOCATION McCarren Airport Terminal 3  
MAILING ADDRESS P. O. Box 11005, Las Vegas, NV 5757 Wayne Newton blvd, Las Vegas, NV  
Subdivision Name \_\_\_\_\_ County: Clark

2 LOCATION NW ¼ NW ¼ Sec 35 T 21S N/S R 61 E Latitude **632763** UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. DW-1244A 162-35-101-020 Longitude **486500.1** N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? yes  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? **103336**

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 61 Feet Depth Cased 60 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	30

Existing Perforations:  
Type of perforation \_\_\_\_\_ Machine Slot \_\_\_\_\_  
Size of perforation \_\_\_\_\_ 0.032  
From \_\_\_\_\_ 30 feet to \_\_\_\_\_ 60 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

5 WATER LEVEL  
Static water level 28' feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Existing grade was 15' below original grade, pulled casing and vacuum out well pack to -35 below original grade (20' below existing grade) and poured cement to 5' from surface.  
Location # **7436**

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: Casing was removed

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 20 feet to 35 feet Cement Grout  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started **8-17-08**  
Date Completed **8-17-08**

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Griffin Dewatering Corp. Contractor  
Address 536 E. Maitland St. Contractor  
Ontario, CA 91761  
Nevada contractor's license number \_\_\_\_\_ issued by the State Contractor's Board C-23 0031246  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1985  
Signed \_\_\_\_\_  
Date **9-12-08**  
By driller performing actual drilling on site or contractor

**DCNR/DWR RECEIVED**  
SEP 16 2008  
**LAS VEGAS OFFICE**

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY