

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. **106920**
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33819

1 OWNER Clark County Aviation ADDRESS AT WELL LOCATION McCarren Airport Terminal 3
MAILING ADDRESS P. O. Box 11005, Las Vegas, NV 5757 Wayne Newton Blvd, Las Vegas, NV
Subdivision Name: _____ County: Clark

2 LOCATION NW ¼ NW ¼ Sec 35 T 21S N/S R 61 E Latitude **63.2370.7** UTM E _____ NAD 27
PERMIT/WAIVER No. DW-1244A 162-35-101-020 Longitude **486.443.5** N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? yes
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? **103333**

4 EXISTING WELL CONSTRUCTION
Depth Drilled 61 Feet Depth Cased 60 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.5	3.6	.280	0	30

Existing Perforations:

Type of perforation	Machine Slot
Size of perforation	0.032
From 30 feet to 60 feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL
Static water level 28' feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
Existing grade was 15' below original grade, pulled casing and vacuum out well pack to -35 below original grade (20' below existing grade) and poured cement to 5' from surface.
Location # **7440**

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: **Casing was removed**

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 20 feet to 35 feet Cement Grout Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started **8-17-08**
Date Completed **8-17-08**

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Griffin Dewatering Corp. Contractor
Address 536 E. Maitland St. Contractor
Ontario, CA 91761
Nevada contractor's license number issued by the State Contractor's Board C-23 0031246
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1985
Signed _____
By driller performing actual drilling on site or contractor
Date **9-12-08**

