

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
 Log No. **107389**  
 Permit No. \_\_\_\_\_  
 Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 34902

1 OWNER Graves Thelma & John J JR ETAL, % Clayton Mtge ADDRESS AT WELL LOCATION 3375 South Polaris Avenue  
 MAILING ADDRESS 3041 W Horizon Ridge Pkwy #155 Las Vegas, Nevada 89102  
 Henderson NV 89052-4437  
 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NW 1/4 NW 1/4 Sec 17 T 21S N/S R 61 E Latitude 36.12795 UTM E  NAD 27  
 PERMIT/WAIVER No. 162-17-102-007 Longitude 115.18565 N  NAD 83/WGS 84  
 Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
 Is this well being plugged because a replacement well was drilled? No  
 Is there an existing well log? Yes  
 If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? 102676

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 25 Feet Depth Cased 25 Feet  
 EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>	<u>PVC</u>	<u>SCH40</u>	<u>0</u>	<u>25</u>

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
 Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:  
 Type of perforator used: \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

Existing Perforations:  
 Type of perforation \_\_\_\_\_ Machine Slot \_\_\_\_\_  
 Size of perforation 0.02  
 From 10 feet to 25 feet  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet

5 WATER LEVEL  
 Static water level 13 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
 Material Used  
 From 0 feet to 25 feet Hole Plug  Pumpe  Poured  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet 3/8"  Pumped  Poured  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
Well # MW-5  
Removal of Well Box  
Pulled Casing 2" x 0' x 25'  
Filled From Bottom To Top With 3/8" Hole Plug

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 10/27/2008  
 Date Completed 10/27/2008

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
 Name Timothy Thompson  
 Contractor  
 Address 750 Pilot Road, Suite F  
 Contractor  
Las Vegas, NV 89119  
 Nevada contractor's license number \_\_\_\_\_  
 issued by the State Contractor's Board  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097  
 Signed [Signature]  
 By driller performing actual drilling on site or contractor  
 Date \_\_\_\_\_

