


**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY 107599

Log No. _____
Permit No. _____
Basin 105



**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 33606

1 OWNER Verizon
MAILING ADDRESS 2849 Ficus Street CA301HJ
Pamona, CA 91766

ADDRESS AT WELL LOCATION 1 mile south of hwy 208, dirt road to top
of hill (2.5 miles)
Subdivision Name: _____ County: Douglas

2 LOCATION NW ¼ NE ¼ Sec 23 T 10N N/S R 21 E
PERMIT/WAIVER No. R-569
Issued by Water Resources Parcel No.

Latitude 38 43'18.78" UTM E NAD 27
Longitude 119 35'33.64" N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NOI? _____

Is there an existing well log? N/A
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 158 Feet Depth Cased 155 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5	10.79	SCH 40	0	155

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From		

5 WATER LEVEL
Static water level 89.68 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Pressure grout from bottom to 5' over drilled upper 5'
N 38 721977
W 119 341674 NAD83

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:

From	feet to	feet	Number of perfs per linear foot
From			

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	155	5	Portland Cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/5.2 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 5/22/2008
Date Completed 5/22/2008

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name WDC Exploration & Wells
Contractor
Address 570 Corinthian Way
Contractor
N. Las Vegas, NV 89030
Nevada contractor's license number 0012852
issued by the State Contractor's Board
Nevada driller's license number issued by the 2057-T3
Division of Water Resources, the on-site driller
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 7.3.08

STATE ENGINEER
17-111111
2008 JUN -6- NAC 6002
RECEIVED

USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 05-08)