


**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**



OFFICE USE ONLY 107603

Log No. _____
Permit No. _____
Basin 105

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 33606

1 OWNER Verizon
MAILING ADDRESS 2849 Ficus Street CA301HJ
Pamona, CA 91766

ADDRESS AT WELL LOCATION 1 mile south of hwy 208, dirt road to top
of hill (2.5 miles)
Subdivision Name: _____ County: Douglas

2 LOCATION NW 1/4 NE 1/4 Sec 23 T 10N N/S R 21 E
PERMIT/WAIVER No. R-569
Issued by Water Resources Parcel No.

Latitude 38 43'19.13" UTM E NAD 27
Longitude 119 35'32.33" N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NOI? _____

Is there an existing well log? N/A
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 143 Feet Depth Cased 140 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

| EXISTING CASING SCHEDULE | | | | |
|--------------------------|------------------------|----------------------------|----------------|--------------|
| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| 4.5 | 10.79 | SCH 40 | 0 | 140 |
| | | | | |
| | | | | |
| | | | | |

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 86.23 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS
Material Used
From 140 feet to 5 feet Portland Cement Pumped Poured
From _____ feet to _____ feet Pumped Poured

6 Additional Notes or Comments

Pressure grout from bottom to 5' over drilled upper 5'
N 86.722074
W 119.591310 NAD03

Neat Cement Fluid Weight 94/5.2 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 5/22/2008
Date Completed 5/22/2008

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name WDC Exploration & Wells Contractor
Address 570 Corinthian Way Contractor
N Las Vegas, NV 89030
Nevada contractor's license number 0012852
issued by the State Contractor's Board
Nevada driller's license number issued by the 2057-T3
Division of Water Resources, the on-site driller
Signed _____
Date 5/25/08
By driller performing actual drilling on site or contractor

USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 05-00)

STATE ENGINEER
19:11:11 6-1007 6002