

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY **107786**

Log No. \_\_\_\_\_  
Permit No. \_\_\_\_\_  
Basin **090**

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **63454**

1 OWNER **CHEVRON ENV. MANAGEMENT CO.** ADDRESS AT WELL LOCATION **947 TADDS BLVD**  
MAILING ADDRESS **6001 BOLLINGER CANYON RD. INCLINE VILLAGE, NV 89451**  
**SAN RAMON, CA 94583** Subdivision Name: \_\_\_\_\_ County: **WASHOE**

2 LOCATION **NW 1/4 15 T 16 N 18 E** Latitude **39° 14.931'** UTM E  NAD 27  
PERMIT/WAIVER No. **SE US-676-8 132-231-10** Longitude **119° 56.829'** N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. **10**

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? **no**  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? **YES NO**  
If yes, what is NDWR well log #? **2234**

4 EXISTING WELL CONSTRUCTION

Depth Drilled **65** Feet Depth Cased **64** Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<b>4</b>		<b>SCH 40 A/C</b>	<b>0</b>	<b>44</b>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: **THE EXISTING 4" WELL WAS COMPLETELY DRILLED OUT AND THE HOLE WAS GRouted BACK**

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
<b>A/C SCREEN</b>	<b>020</b>	<b>44</b>		<b>64</b>	

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level **43** feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used	From	feet to	feet	Material Used	From	feet to	feet
<b>NEAT CEMENT</b>	<b>0</b>		<b>65</b>	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured			
				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured			
				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured			
				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured			
				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured			
				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured			

6 Additional Notes or Comments

**THE ORIGINAL WELL # WAS EX-1-WD**

**- well log # SWR from GPS COORDINATES**

**N 39.248956**

**W 119.946144 NAD27**

Neat Cement Fluid Weight **14** lbs/gal  
Bentonite Grout **3-4** % bentonite  
Date Started **10-6-08**  
Date Completed **10-7-08**

STATE ENGINEERS OFFICE

2008 NOV 10 PM 1:38

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **BOB LONYEAR** Contractor  
Address **3894 RAILROAD AVE, PALMDALE CITY, CA 93551** Contractor  
Nevada contractor's license number issued by the State Contractor's Board **0021976**  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2234**  
Signed **[Signature]** By driller performing actual drilling on site or contractor  
Date **10-11-08**

USE ADDITIONAL SHEETS IF NECESSARY

(Rev 05-06)

RECEIVED