

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY

Log No. 107801
Permit No. _____
Basin 105

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 33605

1 OWNER Verizon ADDRESS AT WELL LOCATION 1 mile south of hwy 208, dirt road to top of hill (2.5 miles)
MAILING ADDRESS 2849 Ficus Street CA301HJ Subdivision Name _____ County Douglas
Pamona, CA 91766

2 LOCATION NW ¼ NE ¼ Sec 23 T 10N N/S R 21 E Latitude 38 43'19.22" UTM E NAD 27
PERMIT/WAIVER No. R-569 Longitude 119 35'32.20" N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NOI? _____
Is there an existing well log? N/A
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 119 Feet Depth Cased 112 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/FT (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2.375</u>	<u>3.65</u>	<u>SCH 40</u>	<u>0</u>	<u>112</u>

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet

5 WATER LEVEL
Static water level 86.48 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments

Pressure grout from bottom to 5' over drilled upper 5'

N 38.722100
W 119.591289 N 7027

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:

From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Material	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>112</u>	feet to <u>5</u>	feet	Portland Cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/5.2 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 5/20/2008
Date Completed 5/20/2008

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name WDC Exploration & Wells
Contractor

Address 570 Corinthian Way
Contractor

N. Las Vegas, NV 89030

Nevada contractor's license number issued by the State Contractor's Board 0012852

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2057-T3

Signed [Signature]
By driller performing actual drilling on site or contractor

Date 7.3.08

(Rev. 05-05)

USE ADDITIONAL SHEETS IF NECESSARY

04-1111 6-NVC 6007

107801