

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

WELL DRILLER'S REPORT

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 30639

1. OWNER CITY OF HENDERSON ADDRESS AT WELL LOCATION WARM SPRINGS RD
 MAILING ADDRESS 3770 Homard Hughes Pkwy + Gibson (Road right of way)
#300 LAS VEGAS, NV 89169
 2. LOCATION SW 1/4 SW 1/4 Sec 2 T 22E N/S R 62N County HENDERSON
 PERMIT NO. H-000534 | 178 02499007 Parcel No. HENDERSON Subdivision Name

3. WORK PERFORMED
 New Well Replace Recondition
 Deepen Abandon Other _____
 4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
 5. WELL TYPE
 Cable Rotary RVC
 Air Other SONC

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
<u>GRAVEL & SAND</u>		<u>0</u>	<u>13</u>	<u>13</u>
<u>small pebbles</u>				
<u>GRAVEL (broken caliche)</u>		<u>13</u>	<u>17</u>	<u>4</u>
<u>muddy clay formation</u>		<u>17</u>	<u>200</u>	
<u>Hole dugged back 200-101'</u>				
<u>Bentrite</u>				
<u>SEA 75-78</u>				

8. WELL CONSTRUCTION
 Depth Drilled 200 Feet Depth Cased 200 Feet
 HOLE DIAMETER (BIT SIZE)
8" From 0 Feet To 200 Feet
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet
 _____ Inches _____ Feet _____ Feet
 CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>	<u>scf 40</u>	<u>PVC</u>	<u>0</u>	<u>80</u>

Perforations:
 Type perforation factory slotted
 Size perforation .020
 From 80 feet to 100 feet
 From _____ feet to _____ feet

Surface Seal: Yes No Seal Type:
 Depth of Seal 0-75 Neat Cement
 Placement Method: Pumped Cement Grout
 Poured Concrete Grout

Gravel Packed: Yes No
 From 101 feet to 78 feet

Date started 4-23-08, 20____
 Date completed 4-25-08, 20____

7. WELL TEST DATA

TEST METHOD:	Bailer	Draw Down (Feet Below Static)	G.P.M.
<u>DN/DNR</u>	<input type="checkbox"/>	<u>RECEIVED</u>	
		<u>MAY 19 2008</u>	
LAS VEGAS OFFICE			

9. WATER LEVEL
 Static water level _____ feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ °F Quality _____

10. DRILLER'S CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.
 Name BOB LANGRISH Contractor
 Address 12464 McNeil DR
SANTA FE SPRINGS, CA 90670
 Nevada contractor's license number 0021976
 issued by the State Contractor's Board
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2198
 Signed Bob Langrish
 By driller performing actual drilling on site or contractor
 Date 5-1-08