

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. **107907**  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. **33595**

1 OWNER **Lucky Champ**  
MAILING ADDRESS **1420 W. Bonanza Rd  
Las Vegas, NV 89106**

ADDRESS AT WELL LOCATION **Same as Owner**

Subdivision Name: \_\_\_\_\_ County: **Clark**

2 LOCATION NW ¼ SE ¼ Sec 21 T 20S N/S R 61 E  
PERMIT/WAIVER No. **13928703008**  
Issued by Water Resources Parcel No.

Latitude **36.17733 N** UTM E  NAD 27  
Longitude **115.16020 W** N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? **Yes**  
If yes, what is replacement well NO? **34988**

Is there an existing well log? **No**  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

| EXISTING CASING SCHEDULE |                     |                         |             |           |
|--------------------------|---------------------|-------------------------|-------------|-----------|
| Size O.D. (Inches)       | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| 1.5                      |                     | Sch 80                  | N/A         | N/A       |
|                          |                     |                         |             |           |
|                          |                     |                         |             |           |
|                          |                     |                         |             |           |

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

5 WATER LEVEL  
Static water level **N/A** feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

Type of perforater used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

6 Additional Notes or Comments  
**Installed New Well**

8 WELL PLUGGING MATERIALS  
Material Used

From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started **4/8/2008**  
Date Completed **4/8/2008**

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **WDC Exploration & Wells**  
Contractor

Address **570 Corinthian Way**  
Contractor  
**N. Las Vegas, NV 89030**

Nevada contractor's license number issued by the State Contractor's Board **0012852**

Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2057 - T3**

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date **4-28-08**

(Rev. 05-05)

**USE ADDITIONAL SHEETS IF NECESSARY**

