


| | | STATE OF NEVADA | | | | OFFICE USE ONLY | |
|--|---------------------|--|--|---|--|--|--------|
| | | DIVISION OF WATER RESOURCES | | | | Log No. | 108204 |
| PRINT OR TYPE ONLY DO NOT WRITE ON BACK | | WELL DRILLER'S PLUGGING REPORT | | | | Permit No. | |
| | | Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340 | | | | Basin | |
| | | | | | NOTICE OF INTENT NO. 33822 | | |
| 1 OWNER Clark County Aviation | | | ADDRESS AT WELL LOCATION McCarren Airport Terminal 3 | | | | |
| MAILING ADDRESS P.O. Box 11005, Las Vegas, Nv. | | | 5757 Wayne Newton Boulevard, Las Vegas, Nv. | | | | |
| | | | Subdivision Name: | | County: Clark | | |
| 2 LOCATION NE ¼ NE ¼ Sec 34 T 21S N 3 R 61 E | | Latitude E632089.9 | | UTM E | | NAD 27 | |
| PERMIT/WAIVER No. DW 1243A | | Parcel No. 162-34-502-010 | | Longitude N486399 | | NAD 83/WGS 84 | |
| 3 TYPE OF WELL | | Is this well being plugged because a replacement well was drilled? | | no | | Is there an existing well log? yes | |
| Domestic Irrigation Test | | Municipal/Industrial Monitor Stock | | If yes, what is replacement well NOI? | | If yes, what is NDWR well log #? 103317 | |
| 4 EXISTING WELL CONSTRUCTION | | | 7 WELL PLUGGING PROCEDURE | | | | |
| Depth Drilled 51 Feet | | Depth Cased 50 Feet | | Was well cleaned out to total depth? yes x no | | Casing was removed | |
| EXISTING CASING SCHEDULE | | | If well was not cleaned out to total depth, please explain why: | | | | |
| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) | | | |
| 6.5 | 3.6 | .280 | 0 | 20 | | | |
| Existing Perforations: | | | Additional Perforations: | | | | |
| Type of perforation | | MACHINE SLOT | | Type of perforator used: | | | |
| Size of perforation | | 0.032 | | | | | |
| From | 20 | feet to | 50 | feet | From | feet to feet Number of perfs per linear foot | |
| From | | feet to | | feet | From | feet to feet Number of perfs per linear foot | |
| From | | feet to | | feet | From | feet to feet Number of perfs per linear foot | |
| From | | feet to | | feet | From | feet to feet Number of perfs per linear foot | |
| From | | feet to | | feet | From | feet to feet Number of perfs per linear foot | |
| 5 WATER LEVEL | | | 8 WELL PLUGGING MATERIALS | | | | |
| Static water level 28' | | feet below land surface | | Material Used | | | |
| Artesian flow | | G.P.M. P.S.I. | | From 20 | feet to 35 | feet Cement Grout Pumped X Poured | |
| Water temperature | | ° F Quality | | From | feet to | feet Pumped Poured | |
| 6 Additional Notes or Comments | | | From | | | | |
| Existing grade was 15' below original grade, pulled casing and vacuum well pack to -35 below original grade (20' below existing) and poured cement to 5' from surface. | | | From | | | | |
| Location #7446 | | | From | | | | |
| WAS SUBMITTED AS SECOND #7429 | | | From | | | | |
| CORRECTED TO 7446 | | | From | | | | |
| | | | Neat Cement Fluid Weight | | lbs/gal | | |
| | | | Bentonite Grout | | % bentonite | | |
| | | | Date Started | | 27-May-08 | | |
| | | | Date Completed | | 27-May-08 | | |
| | | | 9 DRILLER'S CERTIFICATION | | | | |
| | | | This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge. | | | | |
| | | | Name | | Griffin Dewatering Corp. Contractor | | |
| | | | Address | | 536 E. Maitland St. Contractor | | |
| | | | Ontario, Ca 91761 | | | | |
| | | | Nevada contractor's license number | | issued by the State Contractor's Board C-23 0031246 | | |
| | | | Nevada driller's license number issued by the | | Division of Water Resources, the on-site driller M-1985 | | |
| | | | Signed | |  | | |
| | | | Date | | 7-29-08 | | |

(Rev. 05-08)

DENIED/DNR
 RECEIVED

JUL 31 2008

LAS VEGAS OFFICE

USE ADDITIONAL SHEETS IF NECESSARY