STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 108444
Permit No.
Basin ~~HA~~ 104

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 58071

1 OWNER Sierra Estates General Improvement District
MAILING ADDRESS P.O. Box 446 Carson City, NV. 89702

ADDRESS AT WELL LOCATION Between Bucks Way and Shawnee Drive off of Jacks Valley Road
Subdivision Name: County: Douglas

2 LOCATION ~~SW~~ NW ¼ SW ¼ Sec 6 T 14 N/S R 20 E
PERMIT/WAIVER No. 20933 issued by Water Resources Parcel No.

Latitude 39° 06 38.0 N
Longitude 119° 47 18.3 W
UTM E N
☐ NAD 27 ☑ NAD 83/WGS 84

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☒ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI?

Is there an existing well log? yes
If yes, what is NDWR well log #? 6972

4 EXISTING WELL CONSTRUCTION
Depth Drilled 150 Feet Depth Cased 150 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
10.75	34.24	.250	+2	150

Existing Perforations:
Type of perforation slotted
Size of perforation .125x8"

From	105	feet to	150	feet
From		feet to		feet
From		feet to		feet
From		feet to		feet
From		feet to		feet

5 WATER LEVEL
Static water level 65' feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments
Removed 105' of 2" drop pipe and pump from well. Measured static water level @ 65' and depth of well at 147'. Installed 10" Mills Knife to 105' and perforated 5 rows per foot to surface. Removed Mills Knife and installed 2" tremme pipe to 140' and blew debris from well to a depth of 150'. Following day we pumped in 5 yards of neat cement from bottom of well to the surface.

39.106425°N
119.785369°W NAD27

Plugging existing well Log 6972

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: Mills Knife

From	105	feet to	surface	feet	Number of perfs per linear foot 5
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

				Material Used		
From	150'	feet to	surface	feet	neat cement	☒ Pumped ☐ Poured
From		feet to		feet		☐ Pumped ☐ Poured
From		feet to		feet		☐ Pumped ☐ Poured
From		feet to		feet		☐ Pumped ☐ Poured
From		feet to		feet		☐ Pumped ☐ Poured
From		feet to		feet		☐ Pumped ☐ Poured

Neat Cement Fluid Weight 14.7 lbs/gal
Bentonite Grout % bentonite
Date Started 8/13/2009
Date Completed 8/14/2009

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Carson Pump LLC (Contractor)
Address P.O. Box 20159 (Contractor)
Carson City, NV. 89721
Nevada contractor's license number issued by the *State Contractor's Board* 39920A
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2265
Signed (By driller performing actual drilling on site or contractor)
Date 8/20/2009

(Rev. 05-08)

USE ADDITIONAL SHEETS IF NECESSARY