



<b>LOG FOR BORING NO. #1 &amp; #2</b>		<b>JOB NAME:</b> LAS VEGAS PAVING			
<b>DATE STARTED</b> 3/25/09	<b>DATE COMPLETED</b> 3/26/09	<b>LOGGED BY</b> EB	<b>DRILLED BY</b> EB	<b>TYPE OF DRILL RIG</b> #36	<b>JOB NO.</b> 5945
<b>DEPTH OF HOLE</b> 30'	<b>DIAMETER OF HOLE</b> 24"	<b>CASING</b> 8"	<b>PERFORATIONS</b> 20'	<b>SAMPLING METHOD</b>	<b>ELEVATION</b>
<b>LOCATION</b> OAKLEY + RANCHO PN 16204299035				<b>DRILLERS NOTES:</b>	
<b>DEPTH</b>	<b>SAMPLES</b>	<b>GRAPHIC</b>	<b>DESCRIPTION</b>		
10'		▽	BACKFILL ROCK SANDY CLAY ROCK SANDY CLAY ROCK SANDY CLAY CEMENTED GRAVEL SANDY CLAY		
20'					
30'					
40'					
50'					
60'					
70'					
80'					
90'					
100'					

LOGS RECEIVED  
JUN 29 2009  
LAS VEGAS OFFICE

THESE WELLS ARE GRAND TAPS - PIPE BACKFILL WAS AN A.B. FROM -1'. Pulled out some 3" ROCK IN VARIOUS PLACES IN THERE BACKFILL. -27' IS APPROX BOTTOM OF THEIR PIPE.